

Module AMB 35-1CN / -2CN

Product change request: 0094/17

HC V: 01.06.00

EEPROM-V: 01.06.00

Module identification:

Module	Processor / EEPROM	Firmware version		Art. no.	Dependency
		New	Basis		
AMB 35-1CN	M30624FGPFP	---	01.06.00	4800208-06	None
	24C64	EEPROM-V: 01.06.00	---	4800440-01	
AMB 35-2CN	M30624FGPFP	---	01.06.00	4800208-06	
	24C64	EEPROM-V: 01.06.00	---	4800441-01	

Changes:

HC V: 01.06.00		Asd535_V010600.s	486,961 Byte	CRC1: 131F	CRC2: 1F0E	8-2-2012
CR	Type	Description				
--	---	None (see T 140 329)				

Only relevant for production:

EEPROM-V: 01.06.00		AMB35-1CN_EE_V010600.hex	1,945 Byte	CRC1: 2D04	CRC2: 1660	7-21-2017
EEPROM-V: 01.06.00		AMB35-2CN_EE_V010600.hex	1,945 Byte	CRC1: 2AD2	CRC2: 1AF5	7-21-2017
CR	Type	Description				
--	N	Definition of the content of the production data.				

Obligation to replace:

- Hekatron, manufacturing: Yes (as of next production version, FZ 150517)
- Sales: Not relevant

Compatibility:**Notice**

When using the ASD Config configuration software, at least ASD Config version 1.6.0.0 must be used for full functionality.

For file identification purposes, the CRC checksum was checked with the **Validate Program V: 0.4**.